Bathing Water Profile

PROFILE 20 - Update 2014

IL-BAJJA TA' RAS IL-QAWRA (FRA BEN) & IL-BAJJA TAS-SALINA F'SAN PAWL IL-BAĦAR



JUNE 2014





Update to the Bathing Water Profile based on the report by the European Environment Agency issued on 27th May 2014

This is one of a series of 29 profiles that cover all 87 identified bathing waters of the Maltese Islands. Bathing water profiles are established in accordance with Directive 2006/7/EC Article 6, regulation 11, and Schedule III of the Regulations as transposed by Legal Notice 125 of 2008 and amended by Legal Notice 237 of 2011. These regulations concern management of bathing water in relation to the reduction of gastroenteritis and other waterborne health risks originating from faecal sources and other routes of pollution.


In essence, bathing water quality is monitored for 23 weeks each year in different bathing areas in the Maltese Islands by the Environmental Health Directorate. The monitoring period corresponds with the official bathing season that traditionally opens on the third week of May and closes in the third week of October (National Statistics Office, 2004).

Bathing water quality is classified according to Directive 2006/7/EC as 'excellent', 'good', 'sufficient' or 'poor' using the symbols shown in **Figure 1** below. Water quality data from the European Commission was last updated in 2013 (**Figure 2**); the latest figures classify 98.9% of the Maltese Island's bathing waters as of excellent quality, with a very slight decline when compared to the previous year (European Environmental Agency, 2013).

Figure 1: Bathing water star classification from left to right: 'excellent', 'good', 'sufficient' and 'poor'.



Figure 2: Results of bathing water quality in Malta from 2005 to 2013



(European Environment Agency, 2014)

Table 1: Classification of Bathing Waters

	2006/7/EC Classification Based on four years data					
		Excellent		Good		Sufficient
Escherichia coli (cfu/100 ml)	< 250	quality	< 500	quality	> 500	quality
Intestinal Enterococci (cfu/100		Excellent		Good		Sufficient
ml)	< 100	quality	< 200	quality	> 200	quality

Table 2: Water quality classification at the monitoring points (2010-2013)

2013



Excellent Quality

		2006/7/EC Classification			
		Based on four years data			
Bathing Water ID numbers	Year	Escherichia coli	Intestinal Enterococci	Overall Classification	
	2013				
C28		Excellent	Excellent	Excellent	
C29		Excellent	Excellent	Excellent	
C30		Excellent	Excellent	Excellent	
C31		Excellent	Excellent	Excellent	
C32		Excellent	Excellent	Excellent	
	2012				
C28		Excellent	Excellent	Excellent	
C29		Excellent	Excellent	Excellent	
C30		Excellent	Excellent	Excellent	
C31		Excellent	Excellent	Excellent	
C32		Excellent	Excellent	Excellent	
	2011				
C28		Excellent	Excellent	Excellent	
C29		Excellent	Excellent	Excellent	
C30		Excellent	Excellent	Excellent	
C31		Excellent	Excellent	Excellent	
C32		Excellent	Excellent	Excellent	
	2010				
C28		Excellent	Excellent	Excellent	
C29		Excellent	Excellent	Excellent	
C30		Excellent	Excellent	Excellent	

C31	Excellent	Excellent	Excellent
C32	Excellent	Excellent	Excellent

Note that 'C28' is a direct reference to MT0150155500000C28; 'C29' refers to MT0150155500000C29, 'C30' refers to MT0150155500000C30, 'C31' refers to MT0150155500000C31 and 'C32' refers to MT0150155500000C32. The data tabulated above and further information is available at the Environmental Health Directorate website (https://ehealth.gov.mt/HealthPortal/public health/environmental-

health/health inspectorate/env. hlt. risk management/envhealth bathingwater09.aspx).

What should one do if a pollution incident is noticed?

If one sees a water pollution incident, you should immediately contact the Environmental Health Directorate through the Automated Telephone System, which is operated 24 hours. **Phone: 21827146**

Or by calling the Environmental Health Directorate during Office Hours:

Phone: 21337333

Or After Office Hours / Weekends / Public Holidays:

Malta - 79509918 Gozo - 79509919

When a pollution incident is reported or pollution is found to be affecting the water

quality of official bathing areas, an immediate investigation is instigated by the Environmental Health Officers. All possible sources of pollution within the area are checked together with the relevant Competent Authorities. In addition, a resample will be collected to monitor whether the beach is still polluted.

Bathing waters may be closed by the Environmental Health Directorate in accordance with the provisions of Legal Notice 125 of 2008, Regulation 7, until the water quality has improved and levels of bacteria are within mandatory standards in accordance to the provisions of Regulation 8 of the same legal notice.

General Contact Details:

Address:



Environmental Health Directorate Health Inspectorate Services Continental Business Centre Triq il-Ferrovija, Santa Venera, SVR 9018 Malta.

Telephone: +356 21337333

Fax: +356 21344767

Email: complaints.ph@gov.mt

mhi@gov.mt

URL: https://ehealth.gov.mt/HealthPortal/public health/environmental-

health/health inspectorate/env. hlt. risk management/envhealth bathingwater09.aspx

References:

European Environment Agency (2014). Bathing water results 2013— Malta http://www.eea.europa.eu/themes/water/status-and-monitoring/state-of-bathing-water/country-reports-2013-bathing-season/malta-2013-bathing-water-report/view

Environmental Health Directorate - Available:

(https://ehealth.gov.mt/HealthPortal/public health/environmental-health/health inspectorate/env. hlt. risk management/envhealth bathingwater09.aspx)

Version Control				
Version number:	Date:	Next review due:	Comments:	
20.1	June 2013			
20.2	June 2014		Annual data for 2013 added	